

Application No.	Applicant(s)	
10/076.979	6.979 LEPELTIER ET AL.	
Examin r	Art Unit	<u> </u>
Marvin P. Crenshaw	2854	
S (OR REMAINS) CLOSED in to b) or other appropriate commun	his application. If not included ication will be mailed in due course	e. THIS e initiative
<u>d on 4/26/2004</u> .		
the Examiner.		
ve been received. ve been received in Application	No	m the
oddinona nave been received i	ii uiis nauonai stage applicauon no	in the
" of this communication to file a MENT of this application.	reply complying with the requirement	ents
mitted. Note the attached EXAN ves reason(s) why the oath or d	IINER'S AMENDMENT or NOTICE eclaration is deficient.	OF
's Amendment / Comment or in 1.84(c)) should be written on the the header according to 37 CFR osit of BIOLOGICAL MATER	the Office action of drawings in the front (not the back) 1.121(d). RIAL must be submitted. Note the	
6. ☐ Interview Sun Paper No./M 08), 7. ☑ Examiner's A	nmary (PTO-413), ail Date mendment/Comment	
	Examin r Marvin P. Crenshaw Dears In the cover sheet with St. (OR REMAINS) CLOSED in the cover of the community of the cover appropriate community of the saminer. The Examiner. The Examiner of the attached Examiner of the country of this application. The Examiner of the Examiner of the country of the	LEPELTIER ET AL.

Application/Control Number: 10/076,979

Art Unit: 2854

DETAILED ACTION

EXAMINER'S AMENDMENT

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Alfred K. Dassler on June 29, 2004.

The purpose of the examiner's amendment was to further define claims 1 and 11 over the prior art.

The application has been amended as follows:

In claim 1, line 9, after "a", delete "side" and enter - - leg - -.

In claim 1, line 11, after "direction", enter - -, said deformation preventing said infeed triangle from entering said channel slot. - -.

In claim 3, line 3, after "said", delete "side" and enter - - leg - -.

In claim 11, line 12, delete "side" and enter - - leg thereof - -.

Allowable Subject Matter

Claims 1 - 4 and 6 - 11 are allowed.

The following is an examiner's statement of reasons for allowance:

With respect to claim 1 and 11, the prior art does not teach or render obvious the total combination as claimed including an infeed device for drawing a material web into a web-fed rotary printing machine in an infeed direction comprising an infeed triangle having on a leg thereof facing towards an infeed

Art Unit: 2854

channel a deformation extending at least approximately perpendicularly to the infeed direction, said deformation preventing the infeed triangle from entering a channel slot.

Any comments considered necessary by applicant must be submitted no later than the payment of the issue fee and, to avoid processing delays, should preferably accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Marvin P. Crenshaw whose telephone number is (571) 272-2158. The examiner can normally be reached on Monday - Thursday 7:00 - 5:00.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Andrew Hirshfeld can be reached on (571) 272-2168. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Art Unit: 2854

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

MPC

June 30, 2004

Danier J. Colilla Primary Examiner

Art Unit 2854